



## List 5171 - EXOCARB® WH70

Work Material	Hardened Steels			
	D2-S7 55-60 HRC		D2, CPM-9V 60-70 HRC	
Drilling Speed	33-52 SFM		26-42 SFM	
Drill Dia. mm	Speed RPM	Feed IPR	Speed RPM	Feed IPR
2	2,080	0.001 - 0.002	1,670	0.001 - 0.002
3	1,375	0.001 - 0.002	1,100	0.001 - 0.002
4	1,030	0.001 - 0.002	825	0.001 - 0.002
5	825	0.001 - 0.002	660	0.001 - 0.002
6	680	0.001 - 0.002	550	0.001 - 0.002
7	590	0.001 - 0.002	470	0.001 - 0.002
8	515	0.001 - 0.002	410	0.001 - 0.002
9	450	0.001 - 0.002	360	0.001 - 0.002
10	410	0.001 - 0.002	260	0.001 - 0.002
11	375	0.001 - 0.002	300	0.001 - 0.002
12	340	0.001 - 0.002	275	0.001 - 0.002
14	290	0.001 - 0.002	235	0.001 - 0.002
15	270	0.001 - 0.002	220	0.001 - 0.002
16	260	0.001 - 0.002	205	0.001 - 0.002
17	240	0.001 - 0.002	195	0.001 - 0.002
18	230	0.001 - 0.002	180	0.001 - 0.002

1. Use a water soluble oil with high density (5 to 10 times dilution).
2. Tight clamping is critical.
3. For drilling depth > 3D, use a step feed.
4. For materials susceptible to chip packing in the flute, apply a step feed.

## List 5172 - EXOCARB® XH

Work Material	Broken Taps & Drills
Drilling Speed	65-80 SFM
Drill Dia. mm	Speed RPM
2	3,190 - 3,930
3	2,100 - 2,590
4	1,580 - 1,940
5	1,260 - 1,550
6	1,050 - 1,290
7	900 - 1,110
8	790 - 970
9	700 - 860
10	630 - 780
11	570 - 705
12	530 - 650

1. Use a drilling speed of 65-80 SFM.
2. Hand feed of 0.0005~0.001 in/rev is normal.
3. Use a rigid holder.
4. Select a high quality cutting oil and apply in sufficient amounts.
5. This tool should not be used to drill soft steels, aluminum alloys or other soft materials.
6. Resharpener should be done periodically.
7. For through hole processing of heat treated steels, use a spare piece of material underneath the material being drilled as this will prevent breakage caused by sudden torque.
8. Cannot be used to remove forming taps.

